

## ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

---

**Date/Time:** 11/17/04/ 9:40 am

**Site Contact(s):** Kim Myers  
**Phone:** 303-966-7106

**Regulatory Contact:** Denise Onyskiw  
**Phone:** 303-966-6687

**Agency:** CDPHE

---

**Purpose of Contact:** Discuss a breach in the shell of Building 559

---

### Discussion

CDPHE was contacted to discuss the need for a six-point analysis as delineated in the RSOP for Facility Component Removal, Size Reduction, & Decontamination Activities, for removal of the Multi Zone Plenum in room 129 of Building 559.

Room 129 is the mechanical room, which has never had radiological contamination. Building ventilation is still intact and pulls air from the clean areas of Building 559 (i.e., room 129) into the contaminated areas (CA). The exterior walls of the CA are still intact and have not been breached, nor will they be breached until Building 559 undergoes demolition. In order to remove this plenum, the exterior wall of building 129 will be breached, where the plenum intake is located, and the plenum waste removed through this breach. Once the plenum is removed the breach will be contained with plastic containment.

Originally, it was thought that a six-point analysis might be needed; however, after reviewing Section 3.8.1 of the RSOP, CDPHE agreed that the six-point is not required, and that the plenum can be removed.

---

**Contact Record Prepared By:** Kim Myers

---

Required Distribution:

M. Aguilar, USEPA  
S. Bell, DOE-RFPO  
B. Birk, DOE-RFPO

D. Foss, K-H 776/777  
J. Mead, K-H ESS  
G. Morgan, DOE-RFPO


---

Additional Distribution:

D. Kruchek, CDPHE  
D. Onyskiw, CDPHE  
R. Richardella, B559

C. Deck, K-H Legal  
S. Garcia, USEPA  
C. Gilbreath, K-H 771/774  
S. Gunderson, CDPHE  
J. Legare, DOE-RFPO

S. Nesta, K-H RISS  
R. Schassburger, DOE-RFPO  
D. Shelton, K-H ESS  
C. Zahm, K-H Legal  
K. North, K-H ESS/MS



2/2